

**Flood Control Project Maintenance  
Levee Inspections****LMA District Cover Sheet****Spring 2014 Levee Inspection Results****Reclamation District No. 0765 Glide**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
**SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

## Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2014 Levee Inspection Results**

**Reclamation District No. 0765 Glide**

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Right	1.74
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	03/03/2014 - 03/03/2014			
DWR Inspector	Richard Willoughby			
Accompanied By	Everett Lovejoy RD 765			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start		Rating **	M	Issue No.	18
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment				°
					°
DWR ID	DWR_RD0765_01_s _ 2013_18				
Action/Comments					

No Photos

LM Start		Rating **	M	Issue No.	44
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals				°
					°
DWR ID	DWR_RD0765_01_s _ 2012_44				
Action/Comments					

No Photos

LM Start		Rating **	M	Issue No.	46
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training				°
					°
DWR ID	DWR_RD0765_01_s _ 2012_46				
Action/Comments					

No Photos

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.00	Rating **	M	Issue No.	63
LM End	1.74	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation				°
					°
DWR ID	DWR_RD0765_01_s _ 2014_63				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	0.00	Rating **	M	Issue No.	64
LM End	1.74	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation				°
					°
DWR ID	DWR_RD0765_01_s _ 2014_64				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	0.00	Rating **	M	Issue No.	12
LM End	0.11	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.502962 °	38.501373 °
				-121.560112 °	-121.560402 °
DWR ID	DWR_RD0765_01_s _ 2012_12				
Action/Comments					
Fence					

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Levee Inspection Report By Mile - Spring 2014

### Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.05	Rating **	M	Issue No.	3
LM End	0.05	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.502253 °	38.502253 °
				-121.560192 °	-121.560192 °
DWR ID	DWR_RD0765_01_s _ 2012_3				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 1 : richard\_s\_20140303\_065.jpg



Looking north (upstream) at trees on landside slope.

LM Start	0.09	Rating **	A/W	Issue No.	27
LM End	0.09	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.501650 °	38.501650 °
				-121.560290 °	-121.560290 °
DWR ID	DWR_RD0765_01_s _ 2012_27				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.12	Rating **	M	Issue No.	28
LM End	0.19	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.501215 °	38.500271 °
				-121.560432 °	-121.560434 °
DWR ID	DWR_RD0765_01_s _ 2012_28				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 2 : richard\_s\_20140303\_088.jpg



Looking west at trees on landside toe.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.12	Rating **	M	Issue No.	28 (cont)
LM End	0.19	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.501215 °	38.500271 °
				-121.560432 °	-121.560434 °
DWR ID	DWR_RD0765_01_s _ 2012_28				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

Photo 2 of 2 : richard\_s\_20140303\_089.jpg



Looking downstream (south) at trees on landside slope & toe.

LM Start	0.13	Rating **	M	Issue No.	45
LM End	0.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.501181 °	38.501181 °
				-121.560410 °	-121.560410 °
DWR ID	DWR_RD0765_01_f _ 2013_45				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.14	Rating **	M	Issue No.	22
LM End	0.14	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.500928 °	38.500928 °
				-121.560431 °	-121.560431 °
DWR ID	DWR_RD0765_01_s _ 2012_22				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

Photo 1 of 1 : richard\_s\_20140303\_086.jpg



Looking northwest at dense vegetation on landside slope.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.19	Rating **	M	Issue No.	14
LM End	0.35	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.500343 °	38.498032 °
				-121.560507 °	-121.560337 °
DWR ID	DWR_RD0765_01_s _ 2012_14				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.21	Rating **	A/W	Issue No.	25
LM End	0.21	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.500018 °	38.500018 °
				-121.560457 °	-121.560457 °
DWR ID	DWR_RD0765_01_s _ 2012_25				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.24	Rating **	M	Issue No.	49
LM End	0.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.499530 °	38.499530 °
				-121.560490 °	-121.560490 °
DWR ID	DWR_RD0765_01_s _ 2013_49				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Wild berryvines on landside slope.					

Photo 1 of 1 : richard\_s\_20140303\_108.jpg



Looking at wild berryvines or wild roses on landside slope and toe.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.25	Rating **	U	Issue No.	11
LM End	0.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.499405 °	38.499042 °
				-121.560445 °	-121.560430 °
DWR ID	DWR_RD0765_01_s _ 2012_11				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 5 : richard\_s\_20140303\_072.jpg



Looking northeast at overgrown trees on waterside slope.

LM Start	<b>0.25</b>	Rating **	U	Issue No.	<b>11 (cont)</b>
LM End	<b>0.28</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 5 : richard\_s\_20140303\_073.jpg



Looking north at dense trees on waterside slope from fall 2010 inspection.

LM Start	<b>0.25</b>	Rating **	U	Issue No.	<b>11 (cont)</b>
LM End	<b>0.28</b>	Issue Type +	Ma	Location *	WS

Photo 3 of 5 : richard\_s\_20140303\_074.jpg



Looking upstream (north) at dense vegetation and trees from 2011 spring inspection.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.25	Rating **	U	Issue No.	11 (cont)
LM End	0.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.499405 °	38.499042 °
				-121.560445 °	-121.560430 °
DWR ID	DWR_RD0765_01_s _ 2012_11				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

Photo 4 of 5 : richard\_s\_20140303\_075.jpg



Looking north (upstream) at dense trees on landside slope and shoulder. (Spring 2013)

LM Start	<b>0.25</b>	Rating **	U	Issue No.	<b>11 (cont)</b>
LM End	<b>0.28</b>	Issue Type +	Ma	Location *	WS

Photo 5 of 5 : richard\_s\_20140303\_076.jpg



Looking south (downstream) at dense trees on landside slope and shoulder. (Spring 2013)

LM Start	0.26	Rating **	A/W	Issue No.	54
LM End	0.26	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.499177 °	38.499177 °
				-121.560488 °	-121.560488 °
DWR ID	DWR_RD0765_01_f _ 2013_54				
Action/Comments					
Garbage					

Photo 1 of 1 : richard\_s\_20140303\_112.jpg



Looking southwest at garbage on landward shoulder and slope.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.31	Rating **	M	Issue No.	31
LM End	0.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.498516 °	38.498516 °
				-121.560463 °	-121.560463 °
DWR ID	DWR_RD0765_01_f_2012_31				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Wild berryvines on landside toe.					

No Photos

LM Start	0.32	Rating **	M	Issue No.	23
LM End	0.32	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.498453 °	38.498453 °
				-121.560360 °	-121.560360 °
DWR ID	DWR_RD0765_01_s_2012_23				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 1 : richard\_s\_20140303\_087.jpg



Looking north (upstream) at untrimmed trees on waterside shoulder and slope.

LM Start	0.41	Rating **	M	Issue No.	21
LM End	0.41	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.497196 °	38.497196 °
				-121.560147 °	-121.560147 °
DWR ID	DWR_RD0765_01_s_2012_21				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.41	Rating **	M	Issue No.	24
LM End	0.52	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.497125 °	38.495648 °
				-121.560087 °	-121.559391 °
DWR ID	DWR_RD0765_01_s _ 2012_24				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 1 : richard\_s\_20140305\_136.jpg



Looking north (upstream) at untrimmed trees on waterward slope.

LM Start	0.41	Rating **	U	Issue No.	47
LM End	0.41	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.497069 °	38.497069 °
				-121.560106 °	-121.560106 °
DWR ID	DWR_RD0765_01_f _ 2012_47				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Wild berryvines on landside toe.					

Photo 1 of 1 : richard\_s\_20140303\_106.jpg



Looking west at dense berryvines on landside toe.

LM Start	0.43	Rating **	M	Issue No.	32
LM End	0.47	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.496792 °	38.496321 °
				-121.560026 °	-121.559842 °
DWR ID	DWR_RD0765_01_s _ 2012_32				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 1 : richard\_s\_20140303\_093.jpg



Looking southwest at dense vegetation on landside slope and toe.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Levee Inspection Report By Mile - Spring 2014

### Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.47	Rating **	M	Issue No.	55
LM End	0.47	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.496235 °	38.496235 °
				-121.559796 °	-121.559796 °
DWR ID	DWR_RD0765_01_f_2013_55				
Action/Comments					
Garbage					
Inspector Comments: Trash dump on landside slope.					

Photo 1 of 2 : richard\_s\_20140305\_137.jpg



Looking west at garbage on landside slope.

LM Start	<b>0.47</b>	Rating **	M	Issue No.	<b>55 (cont)</b>
LM End	<b>0.47</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : richard\_s\_20140305\_138.jpg



Looking northwest at garbage on landside slope.

LM Start	0.48	Rating **	U	Issue No.	33
LM End	0.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.496217 °	38.495855 °
				-121.559788 °	-121.559586 °
DWR ID	DWR_RD0765_01_s_2012_33				
Action/Comments					
Remove the wild growth other than native grasses from the levee					

Photo 1 of 5 : richard\_s\_20140303\_094.jpg



Looking northwest at trees on landside toe from 2010 fall inspection.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.48	Rating **	U	Issue No.	33 (cont)
LM End	0.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.496217 °	38.495855 °
				-121.559788 °	-121.559586 °
DWR ID	DWR_RD0765_01_s _ 2012_33				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: District removed some of the wild growth on landside slope and toe.					

Photo 2 of 5 : richard\_s\_20140303\_095.jpg



Looking downstream (south) at trees on landside slope & toe.

Photo 3 of 5 : richard\_s\_20140303\_096.jpg



Looking downstream (southwest) at dense vegetation on landside slope.

Photo 4 of 5 : richard\_s\_20140303\_097.jpg



Looking upstream (northwest) at dense vegetation on landside slope.

LM Start	<b>0.48</b>	Rating **	U	Issue No.	<b>33 (cont)</b>
LM End	<b>0.50</b>	Issue Type +	Ma	Location *	LS

<b>* Location</b>
LS : Land Side
WS : Water Side
CR : Crown

<b>** Rating</b>	<b>+ Issue Type</b>
A : Acceptable	Ma : Maintenance Deficiency
M : Minimally Acceptable	Ob : Design & System Obsolescence
U : Unacceptable	En : Enforcement
N : Not Inspected/Rated	
C : Corrected	
A/W : Acceptable but Monitor & Maintain	



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.48	Rating **	U	Issue No.	33 (cont)
LM End	0.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.496217 °	38.495855 °
				-121.559788 °	-121.559586 °
DWR ID	DWR_RD0765_01_s_2012_33				
Action/Comments					
Remove the wild growth other than native grasses from the levee					

Photo 5 of 5 : richard\_s\_20140303\_098.jpg



Looking southwest at dense vegetation on landside slope and toe.

LM Start	0.54	Rating **	M	Issue No.	56
LM End	0.71	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.495350 °	38.493303 °
				-121.559300 °	-121.557620 °
DWR ID	DWR_RD0765_01_f_2013_56				
Action/Comments					
Ditch Inspector Comments: Irrigation ditch at landward toe.					

Photo 1 of 2 : richard\_s\_20140305\_139.jpg



Looking west at irrigation ditch at landward toe.

LM Start	<b>0.54</b>	Rating **	M	Issue No.	<b>56 (cont)</b>
LM End	<b>0.71</b>	Issue Type +	En	Location *	LS

Photo 2 of 2 : richard\_s\_20140305\_140.jpg



Looking southwest at irrigation ditch running along landward toe.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.54	Rating **	M	Issue No.	34
LM End	0.64	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.495347 °	38.494204 °
				-121.559291 °	-121.558313 °
DWR ID	DWR_RD0765_01_s _ 2012_34				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.55	Rating **	M	Issue No.	2
LM End	0.55	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.495263 °	38.495263 °
				-121.559194 °	-121.559194 °
DWR ID	DWR_RD0765_01_s _ 2014_2				
Action/Comments					
Inspector Comments: FS_ID:19578					
EP_NO: 3314					
Repair Type:					
Crossing Status:					
UCIP Comments:					
FIELD_STRUCT_DESC: 16-inch steel pipe hthrough the levee, 4.0 feet below the crown. Cutoff wall around pipe at center of levee. Slant pump on the waterward slope, with 22-inch inlet pipe extending from channel. 16-inch pipe connects to 12-inch steel pipe at landward shoulder, extending to concrete standpipe discharge outlet at the toe. Cobble revetment on waterward slope. (Permit No. 3314-1960)					
FS Date: 5/14/2013					

Photo 1 of 1 : UCIP\_1848.jpg



View of waterward side--pipe, pump, control panels, and electrical conduit.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.57	Rating **	M	Issue No.	10
LM End	0.60	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.495035 °	38.494642 °
				-121.559027 °	-121.558697 °
DWR ID	DWR_RD0765_01_s _ 2012_10				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.69	Rating **	A/W	Issue No.	35
LM End	0.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.493596 °	38.493077 °
				-121.557832 °	-121.557451 °
DWR ID	DWR_RD0765_01_s _ 2012_35				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.71	Rating **	A/W	Issue No.	15
LM End	0.71	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.493392 °	38.494171 °
				-121.557640 °	-121.558253 °
DWR ID	DWR_RD0765_01_s _ 2012_15				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.76	Rating **	M	Issue No.	50
LM End	0.80	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.492713 °	38.492176 °
				-121.557224 °	-121.556893 °
DWR ID	DWR_RD0765_01_s _ 2013_50				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 1 : richard\_s\_20140303\_109.jpg




Looking northwest at vegetation on landside slope.

LM Start	0.78	Rating **	M	Issue No.	36
LM End	0.81	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.492392 °	38.492034 °
				-121.557026 °	-121.556820 °
DWR ID	DWR_RD0765_01_s _ 2012_36				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

No Photos

LM Start	0.87	Rating **	A/W	Issue No.	17
LM End	0.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.491283 °	38.489771 °
				-121.556360 °	-121.555451 °
DWR ID	DWR_RD0765_01_s _ 2012_17				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 6 : richard\_s\_20140303\_079.jpg



Looking downstream (south) at dense trees on landside slope and toe.

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.87	Rating **	A/W	Issue No.	17 (cont)
LM End	0.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.491283 °	38.489771 °
				-121.556360 °	-121.555451 °
DWR ID	DWR_RD0765_01_s _ 2012_17				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 2 of 6 : richard\_s\_20140303\_080.jpg



Looking upstream (north) at dense trees on landside slope and toe.

LM Start	<b>0.87</b>	Rating **	A/W	Issue No.	<b>17 (cont)</b>
LM End	<b>0.99</b>	Issue Type +	Ma	Location *	LS

Photo 3 of 6 : richard\_s\_20140303\_081.jpg



Looking south at dense trees on landside shoulder and slope.  
(November 2011)

LM Start	<b>0.87</b>	Rating **	A/W	Issue No.	<b>17 (cont)</b>
LM End	<b>0.99</b>	Issue Type +	Ma	Location *	LS

Photo 4 of 6 : richard\_s\_20140303\_082.jpg



Looking southwest at dense trees on landside slope and toe spring 2012.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.87	Rating **	A/W	Issue No.	17 (cont)
LM End	0.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.491283 °	38.489771 °
				-121.556360 °	-121.555451 °
DWR ID	DWR_RD0765_01_s _ 2012_17				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 5 of 6 : richard\_s\_20140303\_083.jpg



Looking southwest at dense vegetation on landward slope.

LM Start	<b>0.87</b>	Rating **	A/W	Issue No.	<b>17 (cont)</b>
LM End	<b>0.99</b>	Issue Type +	Ma	Location *	LS

Photo 6 of 6 : richard\_s\_20140305\_141.jpg



Looking south at trimmed trees and vegetation on landside slope and toe.

LM Start	0.96	Rating **	M	Issue No.	20
LM End	0.96	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.490127 °	38.490127 °
				-121.555594 °	-121.555594 °
DWR ID	DWR_RD0765_01_s _ 2014_20				
Action/Comments					
Inspector Comments: FS_ID:19579					

Photo 1 of 1 : UCIP\_1852.jpg



Pipe section visible at waterward toe.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.97	Rating **	A/W	Issue No.	81
LM End	0.97	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.489962 °	38.489962 °
				-121.555573 °	-121.555573 °
DWR ID	DWR_RD0765_01_s _ 2012_81				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Dense berryvines on landside slope.					

Photo 1 of 5 : richard\_s\_20140303\_117.jpg



Looking west at dense berryvines and wildroses on landside shoulder and slope. (November 2011)

LM Start	<b>0.97</b>	Rating **	A/W	Issue No.	<b>81 (cont)</b>
LM End	<b>0.97</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 5 : richard\_s\_20140303\_118.jpg



Looking northwest at vines on landside toe spring 2012.

LM Start	<b>0.97</b>	Rating **	A/W	Issue No.	<b>81 (cont)</b>
LM End	<b>0.97</b>	Issue Type +	Ma	Location *	LS

Photo 3 of 5 : richard\_s\_20140303\_119.jpg



Looking west at trimmed trees on landward slope.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.97	Rating **	A/W	Issue No.	81 (cont)
LM End	0.97	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.489962 °	38.489962 °
				-121.555573 °	-121.555573 °
DWR ID	DWR_RD0765_01_s _ 2012_81				
Action/Comments					
Remove the wild growth other than native grasses from the levee					

Photo 4 of 5 : richard\_s\_20140305\_142.jpg



Looking southwest at trimmed trees and vegetation on landside slope and toe.

LM Start	<b>0.97</b>	Rating **	A/W	Issue No.	<b>81 (cont)</b>
LM End	<b>0.97</b>	Issue Type +	Ma	Location *	LS

Photo 5 of 5 : richard\_s\_20140305\_143.jpg



Looking northwest at trimmed trees and vegetation on landside slope and toe.

LM Start	0.99	Rating **	M	Issue No.	51
LM End	0.99	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.489653 °	38.489653 °
				-121.555399 °	-121.555399 °
DWR ID	DWR_RD0765_01_s _ 2013_51				
Action/Comments					
Ditch					

Photo 1 of 1 : richard\_s\_20140303\_110.jpg



Looking southwest at irrigation ditch on landward toe.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	0.99	Rating **	U	Issue No.	6
LM End	1.15	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.489664 °	38.487617 °
				-121.555370 °	-121.554200 °
DWR ID	DWR_RD0765_01_f_2012_6				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 2 : richard\_s\_20140305\_134.jpg



Looking north (upstream) at untrimmed trees on waterward slope.

LM Start	<b>0.99</b>	Rating **	U	Issue No.	<b>6 (cont)</b>
LM End	<b>1.15</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : richard\_s\_20140305\_135.jpg



Looking south (downstream) at untrimmed trees on waterward slope.

LM Start	1.02	Rating **	A/W	Issue No.	40
LM End	1.02	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.489283 °	38.489283 °
				-121.555223 °	-121.555223 °
DWR ID	DWR_RD0765_01_s_2012_40				
Action/Comments					
Trees / Woody Vegetation					

Photo 1 of 1 : richard\_s\_20140303\_104.jpg



Looking southwest at fig trees and other trees on landside slope and toe.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.04	Rating **	A/W	Issue No.	16
LM End	1.04	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.489036 °	38.489036 °
				-121.555054 °	-121.555054 °
DWR ID	DWR_RD0765_01_f_2012_16				
Action/Comments					
Landscaping					
Inspector Comments: Cactus at landside toe.					


Photo 1 of 1 : richard\_s\_20140303\_078.jpg



Looking west at cactus at landside toe.

LM Start	1.08	Rating **	M	Issue No.	37
LM End	1.08	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.488503 °	38.488503 °
				-121.554757 °	-121.554757 °
DWR ID	DWR_RD0765_01_s_2012_37				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 4 : richard\_s\_20140303\_099.jpg



Looking downstream (south) at trees on landside slope &amp; toe from 2010 fall inspection.

LM Start	<b>1.08</b>	Rating **	M	Issue No.	<b>37 (cont)</b>
LM End	<b>1.08</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 4 : richard\_s\_20140303\_100.jpg



Looking west at trees on landside slope &amp; toe.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.08	Rating **	M	Issue No.	37 (cont)
LM End	1.08	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.488503 °	38.488503 °
				-121.554757 °	-121.554757 °
DWR ID	DWR_RD0765_01_s _ 2012_37				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood					


Photo 3 of 4 : richard\_s\_20140303\_101.jpg



Looking downstream (southwest) at dense trees on landside slope and toe.

LM Start	<b>1.08</b>	Rating **	M	Issue No.	<b>37 (cont)</b>
LM End	<b>1.08</b>	Issue Type +	Ma	Location *	LS

Photo 4 of 4 : richard\_s\_20140303\_102.jpg



Looking southwest at trees on landward slope.

LM Start	1.10	Rating **	M	Issue No.	38
LM End	1.16	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.488279 °	38.487465 °
				-121.554615 °	-121.554117 °
DWR ID	DWR_RD0765_01_s _ 2012_38				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.10	Rating **	M	Issue No.	30
LM End	1.10	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.488151 °	38.488151 °
				-121.554513 °	-121.554513 °
DWR ID	DWR_RD0765_01_s_2014_30				
Action/Comments					
Inspector Comments: FS_ID:19580					
EP_NO: N/A					
Repair Type:					
Crossing Status:					
UCIP Comments:					
FIELD_STRUCT_DESC: 6-inch steel pipe through the levee, 2.5 feet below the crown. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (RM 50.15).					
FS Date: 5/14/2013					

Photo 1 of 1 : UCIP\_1857.jpg



Overview of landward side--concrete standpipe and control panel located at toe.

LM Start	1.15	Rating **	A/W	Issue No.	48
LM End	1.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.487645 °	38.487645 °
				-121.554233 °	-121.554233 °
DWR ID	DWR_RD0765_01_f_2012_48				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Wild berryvines at landside toe.					

Photo 1 of 1 : richard\_s\_20140303\_107.jpg



Looking southwest at dense vegetation on landside slope and toe.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.16	Rating **	M	Issue No.	9
LM End	1.16	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.487473 °	38.487473 °
				-121.554080 °	-121.554080 °
DWR ID	DWR_RD0765_01_s _ 2012_9				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	1.19	Rating **	M	Issue No.	43
LM End	1.22	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.487127 °	38.486702 °
				-121.553910 °	-121.553652 °
DWR ID	DWR_RD0765_01_s _ 2012_43				
Action/Comments					
Building					

Photo 1 of 1 : richard\_s\_20140303\_105.jpg



Looking northwest at buildings along landside toe.

LM Start	1.32	Rating **	C	Issue No.	39
LM End	1.34	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.485485 °	38.485218 °
				-121.552931 °	-121.552772 °
DWR ID	DWR_RD0765_01_f _ 2013_39				
Action/Comments					
Repair slope instability.					
Inspector Comments: LMA repaired shoulder damage on waterward shoulder.					

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Levee Inspection Report By Mile - Spring 2014

### Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.32	Rating **	M	Issue No.	26
LM End	1.35	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.485280 °	38.485002 °
				-121.552860 °	-121.552687 °
DWR ID	DWR_RD0765_01_s _ 2012_26				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	1.36	Rating **	A/W	Issue No.	7
LM End	1.36	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.484877 °	38.484877 °
				-121.552540 °	-121.552540 °
DWR ID	DWR_RD0765_01_s _ 2012_7				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 2 : richard\_s\_20140303\_068.jpg



Looking upstream (north) at dense vegetation on waterside slope.

LM Start	<b>1.36</b>	Rating **	A/W	Issue No.	<b>7 (cont)</b>
LM End	<b>1.36</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : richard\_s\_20140303\_069.jpg



Looking southeast at dense vegetation on waterside slope. (Fall Inspection 2012)

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.41	Rating **	M	Issue No.	4
LM End	1.41	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.484316 °	38.484316 °
				-121.552115 °	-121.552115 °
DWR ID	DWR_RD0765_01_s_2012_4				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 1 : richard\_s\_20140305\_132.jpg




Looking north at untrimmed trees on waterward slope.

LM Start	1.43	Rating **	C	Issue No.	57
LM End	1.43	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.483987 °	38.483987 °
				-121.551964 °	-121.551964 °
DWR ID	DWR_RD0765_01_f_2013_57				
Action/Comments					
Tree or limb					
Inspector Comments: Downed tree limbs on landward toe.					

No Photos

LM Start	1.44	Rating **	M	Issue No.	5
LM End	1.47	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.483925 °	38.483530 °
				-121.551845 °	-121.551587 °
DWR ID	DWR_RD0765_01_s_2012_5				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 2 : richard\_s\_20140303\_066.jpg



Looking upstream (north) at dense trees on waterside slope.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.44	Rating **	M	Issue No.	5 (cont)	
LM End	1.47	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Trim / Thin Trees			38.483925 °	38.483530 °	
				-121.551845 °	-121.551587 °	
DWR ID	DWR_RD0765_01_s _ 2012_5					
Action/Comments						
Thin trees to allow visibility of the ground and room to flood fight.						

Photo 2 of 2 : richard\_s\_20140303\_067.jpg



Looking north at dense vegetation on waterside slope. (Fall Inspection 2012)

LM Start	1.46	Rating **	A/W	Issue No.	41
LM End	1.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.483640 °	38.483640 °
				-121.551727 °	-121.551727 °
DWR ID	DWR_RD0765_01_s _ 2012_41				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	1.48	Rating **	C	Issue No.	58
LM End	1.48	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.483379 °	38.483379 °
				-121.551545 °	-121.551545 °
DWR ID	DWR_RD0765_01_f _ 2013_58				
Action/Comments					
Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comments: Slope damage on landward slope.					

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.48	Rating **	A/W	Issue No.	19
LM End	1.48	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.483353 °	38.483353 °
				-121.551457 °	-121.551457 °
DWR ID	DWR_RD0765_01_f_2013_19				
Action/Comments					
Repair the levee slope damaged by vehicle traffic and prevent access					

Photo 1 of 3 : richard\_s\_20140303\_084.jpg



Looking southeast at slope damage on waterward slope.

LM Start	<b>1.48</b>	Rating **	A/W	Issue No.	<b>19 (cont)</b>
LM End	<b>1.48</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 3 : richard\_s\_20140303\_085.jpg



Looking southwest at slope damage on waterward slope.

LM Start	<b>1.48</b>	Rating **	A/W	Issue No.	<b>19 (cont)</b>
LM End	<b>1.48</b>	Issue Type +	Ma	Location *	WS

Photo 3 of 3 : richard\_s\_20140305\_131.jpg



Looking north at repaired slope damage on waterward slope.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.50	Rating **	A/W	Issue No.	42
LM End	1.51	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.483170 °	38.482965 °
				-121.551367 °	-121.551265 °
DWR ID	DWR_RD0765_01_s _ 2012_42				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	1.52	Rating **	M	Issue No.	1
LM End	1.73	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.482893 °	38.480257 °
				-121.551121 °	-121.549458 °
DWR ID	DWR_RD0765_01_s _ 2012_1				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 2 : richard\_s\_20140305\_124.jpg



Looking southeast at vegetation on waterward slope.

Photo 2 of 2 : richard\_s\_20140305\_125.jpg



Looking north at vegetation on waterward slope.

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.54	Rating **	M	Issue No.	29
LM End	1.54	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.482665 °	38.482665 °
				-121.551036 °	-121.551036 °
DWR ID	DWR_RD0765_01_s _ 2012_29				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 5 : richard\_s\_20140303\_090.jpg



Looking south at dense vegetation on landside shoulder and slope.  
(November 2011)

LM Start	<b>1.54</b>	Rating **	M	Issue No.	<b>29 (cont)</b>
LM End	<b>1.54</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 5 : richard\_s\_20140303\_091.jpg



Looking south at dense vegetation on landside slope and toe spring  
2012.

LM Start	<b>1.54</b>	Rating **	M	Issue No.	<b>29 (cont)</b>
LM End	<b>1.54</b>	Issue Type +	Ma	Location *	LS

Photo 3 of 5 : richard\_s\_20140303\_092.jpg



Looking southwest at vegetation on landside slope and toe. (Fall  
Inspection 2012)

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.54	Rating **	M	Issue No.	29 (cont)
LM End	1.54	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.482665 °	38.482665 °
				-121.551036 °	-121.551036 °
DWR ID	DWR_RD0765_01_s _ 2012_29				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 4 of 5 : richard\_s\_20140305\_145.jpg



Looking southwest at vegetation on landside slope.

LM Start	<b>1.54</b>	Rating **	M	Issue No.	<b>29 (cont)</b>
LM End	<b>1.54</b>	Issue Type +	Ma	Location *	LS

Photo 5 of 5 : richard\_s\_20140305\_146.jpg



Looking southwest at berryvines on landside slope.

LM Start	1.56	Rating **	A/W	Issue No.	59
LM End	1.56	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.482402 °	38.482402 °
				-121.550867 °	-121.550867 °
DWR ID	DWR_RD0765_01_f _ 2013_59				
Action/Comments					
Prunings					

Photo 1 of 1 : richard\_s\_20140303\_115.jpg



Looking west a prunings on landward berm.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.56	Rating **	A/W	Issue No.	8
LM End	1.56	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.482414 °	38.482414 °
				-121.550804 °	-121.550804 °
DWR ID	DWR_RD0765_01_f_2013_8				
Action/Comments					
Schedule repair of erosion site prior to the next inspection. Inspector Comments: Erosion located around metal walkway on waterward shoulder and slope.					

Photo 1 of 4 : richard\_s\_20140303\_070.jpg



Looking south at erosion on waterward shoulder.

LM Start	<b>1.56</b>	Rating **	A/W	Issue No.	<b>8 (cont)</b>
LM End	<b>1.56</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 4 : richard\_s\_20140303\_071.jpg



Looking west at erosion on waterward shoulder and slope.

LM Start	<b>1.56</b>	Rating **	A/W	Issue No.	<b>8 (cont)</b>
LM End	<b>1.56</b>	Issue Type +	Ma	Location *	WS

Photo 3 of 4 : richard\_s\_20140305\_129.jpg



Looking north at repaired erosion on waterward should.

**\* Location**  
LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Levee Inspection Report By Mile - Spring 2014

### Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.56	Rating **	A/W	Issue No.	8 (cont)	
LM End	1.56	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.482414 °	38.482414 °	
				-121.550804 °	-121.550804 °	
DWR ID	DWR_RD0765_01_f_2013_8					
Action/Comments						
Schedule repair of erosion site prior to the next inspection.						

Photo 4 of 4 : richard\_s\_20140305\_130.jpg



Looking west at repaired erosion on waterward shoulder.

LM Start	1.57	Rating **	U	Issue No.	60
LM End	1.63	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.482300 °	38.481482 °
				-121.550808 °	-121.550283 °
DWR ID	DWR_RD0765_01_f_2013_60				
Action/Comments					
Ditch Inspector Comments: Old Irrigation ditch at landward toe.					

Photo 1 of 1 : richard\_s\_20140303\_116.jpg



Looking southwest at irrigation ditch on landward toe.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.57	Rating **	M	Issue No.	61
LM End	1.57	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.482290 °	38.482290 °
				-121.550769 °	-121.550769 °
DWR ID	DWR_RD0765_01_s _ 2014_61				
Action/Comments					
Inspector Comments: FS_ID:19581					
EP_NO: 12862					
Repair Type:					
Crossing Status:					
UCIP Comments:					
FIELD_STRUCT_DESC: 14-inch steel pipe sleeved through 16-inch steel pipe through the levee, 20.3 feet below the crown. Gate valve on the waterward side. Pump on piling (platform) in the stream, walkway to the pump. Service pole on the landward slope. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (RM 49.68). 14-inch steel pipe added under Permit No. 12826 (1980). Annular gap grouted.					
FS Date: 5/14/2013					

Photo 1 of 1 : UCIP\_1864.jpg



View of waterward side--walkway, support piles, access gate and pump.

LM Start	1.57	Rating **	M	Issue No.	62
LM End	1.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments				o
					o
DWR ID	DWR_RD0765_01_s _ 2014_62				
Action/Comments					
Garbage					

No Photos

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.67	Rating **	U	Issue No.	53
LM End	1.67	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees				° 38.480892 °
					° -121.549654 °
DWR ID	DWR_RD0765_01_s _ 2013_53				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 1 : richard\_s\_20140305\_128.jpg



Looking north at dense vegetation on waterward slope.

LM Start	1.69	Rating **	U	Issue No.	13
LM End	1.70	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.480763 °	38.480632 °
				-121.549581 °	-121.549543 °
DWR ID	DWR_RD0765_01_s _ 2012_13				
Action/Comments					
Prunings					
Inspector Comments: Large tree branch on waterward slope.					

Photo 1 of 3 : richard\_s\_20140303\_077.jpg



Looking northeast at tree limbs on waterward slope.

LM Start	<b>1.69</b>	Rating **	U	Issue No.	<b>13 (cont)</b>
LM End	<b>1.70</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 3 : richard\_s\_20140305\_126.jpg



Looking north at large tree limb on waterward slope.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2014 03/03/2014	Richard Willoughby

LM Start	1.69	Rating **	U	Issue No.	13 (cont)
LM End	1.70	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.480763 °	38.480632 °
				-121.549581 °	-121.549543 °
DWR ID	DWR_RD0765_01_s _ 2012_13				
Action/Comments					
Prunings					


Photo 3 of 3 : richard\_s\_20140305\_127.jpg



Looking east at large tree limb on waterward slope.

LM Start	1.71	Rating **	U	Issue No.	52
LM End	1.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.480519 °	38.480164 °
				-121.549513 °	-121.549445 °
DWR ID	DWR_RD0765_01_s _ 2013_52				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 1 : richard\_s\_20140303\_111.jpg



Looking north (upstream) at dense trees on landside slope.

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement